



Point Spring & Driveshaft Co.

Since 1926

PARTS • SERVICE • EXPERIENCE • SOLUTIONS



Voyager®



REVOLUTIONARY HUB INSTALLED, UNITIZED SEAL

The Voyager® wheel seal is designed for regional route trucks, city traffic and coach applications. Rugged design, simple installation and proven performance make Voyager the right choice for fleets seeking a superior seal for everyday stop-and-go traffic environments.

Part No.	Description	Price
373-0123	Oil Seal Voyager	\$37.99
373-0143	Oil Seal Voyager	\$37.99
383-0136	Oil Seal Voyager	\$38.99
383-0164	Oil Seal Voyager	\$51.99
393-0173	Oil Seal Voyager	\$51.99


purchase a combination of 12 seals and receive a free set of seal installers from Stemco



STEMCO HUB CAPS

The industry leader, providing proven protection and exceptional value for every fleet

Part No.	Description	Price
300-4009	Hub Cap Tn Axle w/Gasket	\$11.99
340-4024	Hub Cap	\$36.99
340-4195	Hub Cap	\$32.99
342-4024	Dirt Exclusion Grease Hub Cap	\$45.99
343-4024	Hub Cap with Pipe Plug	\$39.99
343-4195	Hub Cap with Pipe Plug	\$34.99
343-4370	Hubcap, PSI, Oil, Short Tube	\$30.99
343-4372	Hubcap PSI Oil	\$39.99
360-4024	Defender Hub Cap w/Red Plug FF Blk	\$15.99



NO TORQUE WRENCH REQUIRED

STEMCO is changing the game on wheel ends again! With the Auto-Torq axle fastener, installation has never been easier. Auto-Torq sets the wheel end in optimum bearing adjustment for maximum life.

Part No.	Description	Included Seal	Price
480-4743-XR	AutoTorq - TN axle nut and seal kit	373-0423	\$121.99
480-4723-XR	AutoTorq - TP axle nut and seal kit	373-0443	\$127.99

www.pointspring.com

Promotional pricing valid through August 31, 2024

KIT MASTERS


FAN CLUTCH EXPERTS

KYSOR STYLE FAN CLUTCH REBUILD KITS

Replaces most Borg Warner style fan clutches



8901N



24-256



24-256-1



14-256



9500HP

Part No.	Description	Price
24-256	2-Speed GoldTop Rebuild Kit - 2 Pulley Bearings	\$809.99
24-256-1	2-Speed GoldTop Rebuild Kit - 1 Pulley Bearing	\$809.99
14-256	GoldTop Fan Clutch Rebuild Kit - 2.56" Fan Pilot, 2 Pulley Bearings	\$538.99
9500HP	9.5 Inch Fan Clutch Rebuild Kit	\$466.99
8901N	Kysor-Style Fan Clutch	\$344.99

Corresponding Bearing Kits



8581-01

8582-01

Part No.	Description	Price
8581-01	Kysor-Style Hub Bearing Kit - Includes one 6209 bearing and one 6207 bearing	\$96.99
8582-01	Kysor-Style Hub Bearing Kit - Includes one 3207 bearing	\$96.99

failure to change bearings will void clutch warranty

Promotional pricing valid through August 31, 2024

POINT SPRING & DRIVESHAFT CO. LOCATIONS

NEVILLE ISLAND, PA
7309 Grand Avenue
Neville Island, PA 15225
Ph: 412-264-6714
Fx: 412-264-6722
(800) 837-4713

NEW CASTLE, PA
1001 Harbor Street
New Castle, PA 16101
Ph: 724-658-9076
Fx: 724-658-8746
(800) 837-8713

TROY, PA
68 Canton Street
Troy, PA 16947
Ph: 570-297-5555
Fx: 570-297-5510
(855) 297-6380

SARVER, PA
555 North Pike Road
Sarver, PA 16055
Ph: 724-352-3340
Fx: 724-352-5311

INDIANA, PA
1849 South Sixth
Street Suite 5
Indiana, PA 15701
Ph: 724-463-3710

GREENSBURG, PA
1967 Route 66
Greensburg, PA 15601
Ph: 724-834-0750
Fx: 724-834-8747
(800) 837-9713

MEADVILLE, PA
11377 Mercer Pike
Meadville, PA 16335
Ph: 814-724-7746
Fx: 814-724-7747
(800) 724-7751

CLEARFIELD, PA
1729 Industrial Park Rd.
P.O. Box 1206
Clearfield, PA 16830
Ph: 814-765-9684
Fx: 814-765-1577
(800) 252-3585

FAIRMONT, WV
274 Van Kirk Drive
Fairmont, WV 26554
Ph: 304-534-3306
Fx: 304-534-5079
(800) 837-1713

AKRON, OH
1250 Triplett Blvd.
Akron, OH 44306
Ph: 330-724-1111
Fx: 330-724-1895
(800) 826-0673



Point Spring & Driveshaft Co.
Since 1926

follow us on social media



Point Spring & Driveshaft Co.



@Pointspring1926